




Certified Inspection Report For: Llanharry Community Council Groes Sannor, Degar Road Llanharry, Pontyclun, Mid Glamorgan CF72 9JX		Contact: Gill Lewis Tel: 01443 223 007 Mobile: E-mail: llanharrycc@live.co.uk Order No: 322800		Site Address: <p style="text-align: center;">The Recreation Field (Opp shops) junction of Sycamore Road Ty Isaf, Llanharry CF72 9LJ</p>			SHEET 1 of 3
---	--	---	--	--	--	--	---

DESCRIPTION OF PRODUCTS INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY	PRODUCT CODE	DESCRIPTION OF PARTS REQUIRED	UNIT PRICE	TOTAL	
<u>Area 1 (open area)</u>									
Teen Shelter on Tarmac	Streetmain	L	Generally satisfactory but monitor vandalism at the nut cover caps and recommend offensive graffiti is removed from the panels					£0.00	
Ball Court on Tarmac	Unknown	M	Inspected to the requirements and recommendations of BS EN 15312: 2007 relating to Free access multi-sports equipment. A clearly visible sign shall be provided in a prominent position, including at least the following: This equipment is not intended for children less than 3yrs Warning "Do not climb on the framework or nets" Warning "Do not hang on the ring" (if provided) Warning "Do not wear rings or other jewellery as these can get caught and cause injury" Name and phone number of administrator/maint contact; Phone number to call in case of accident. (Ref BS EN 15312: 2007 + A1: 2010 (E) Section 8)			<i>(Customer Information Only)</i> <i>Refer to Wicksteed Sales Department for further details on Signs.</i>			
Boulder Cluster on Grass	Natural Play	M	Fire damage to 30 x fixing caps recommend replace				<i>Refer to Manufacturer for Spare Parts</i>		
			Satisfactory condition.						
<u>Area 2 (enclosed area)</u>									
High Pedestal Slide on Black Wet Pour	Wicksteed 2005/6	L	Generally satisfactory but monitor the surface condition						
Cable Runway on Black Wet Pour	Record 2008	MH	Suspension chain has been knotted, reducing the cable clearance & creating potential finger entrapment hazards recommend the suspension and seat are replaced and adjust main cable tension if required to increase ground clearance to 400mm under 130kg load	1	5082-330	<i>(Customer Information Only)</i> Cableway Seat & <u>Twist Link</u> Chain Assembly	£144.00		
		L	Monitor wear at the buffer tyres						
		L	Monitor corrosion from inside one terminus upright.						
		L	Monitor gaps in safety surface approx 28m						
Multiplay Unit Ref RP692 on Black Wet Pour	Record 2003	M	Damage to barrier upright (yellow) recommend repair.						
		M	Recommend the surface is cleaned to remove algal growth and reduce slip hazards						

 	Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028 www.wicksteed.co.uk	INDICATION OF RISK RATING ASSESSMENT MH/H MEDIUM HIGH & HIGH RISK - See Introductory Notes M MEDIUM RISK - See Introductory Notes VL/L VERY LOW & LOW RISK - See Introductory Notes	INSPECTED BY : C. Newell DATE : 26.1.2016	PARTS SUB TOTAL BALANCE C / FORWARD PARTS TOTAL EXC. CARRIAGE & VAT. LABOUR COST TO FIT PARTS * Based on all works ordered	(E&O.E.)	£0.00 £0.00 £0.00 See Sheet 3

Certified Inspection Report For: Llanharry Community Council Groes Sannor, Degar Road Llanharry, Pontyclun, Mid Glamorgan CF72 9JX			Contact: Gill Lewis Tel: 01443 223 007 Mobile: E-mail: llanharrycc@live.co.uk Order No: 322800		Site Address: The Recreation Field (Opp shops) junction of Sycamore Road Ty Isaf, Llanharry CF72 9LJ			SHEET 2 of 3
DESCRIPTION OF PRODUCTS INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY	PRODUCT CODE	DESCRIPTION OF PARTS REQUIRED	UNIT PRICE	TOTAL
Roundabout Ref RP426 on Black/Blue Fleck Wet Pour	Record 2004	M L	Bearings are worn, creating potential entrapment hazards the platform, recommend the bearings are replaced Recommend the painting of this unit is included within your current maintenance schedule (note: ensure surface coatings are free of harmful contents to avoid potential toxic hazards, ref BS EN 1176-1:2008, clause 4.1.1)			<i>Refer back to manufacturer for spares</i> We are unable to quote for repairs to this swing as we are unable to identify the manufacturer. Quotation to remove and install new swing available upon request		
Ben Nevis Climber on Black Wet Pour	Wicksteed 2005/6		Satisfactory condition.					
1.9m 1 Bay 2 Seat Swing 2 x Cradle Seats on Black Wet Pour	G L Jones	L L	Generally satisfactory but monitor paint condition at the top bar Monitor surface shrinkage at the edges, further deterioration could create trip hazards or encourage vandalism					
2.4M 1 Bay Metal Swing 2 x Flat Seats on Wet Pour	Unknown	M MH M MH	Monitor shackle/bush support, manufacturer not known, replacement parts might not be available and further deterioration could result in failure under load Seat eyebolts rotate recommend tighten or replace. Seats are set too low, 350mm minimum ground clearance recommended (320mm actual), no adjustment possible with existing chains Corrosion in swing top bar, further deterioration could result in material or structural failure, recommend the unit is repaired or replaced					
Duck Spring Mobile on Red / Black / Blue Wet Pour	Playworld Systems		Satisfactory condition.					
Seahorse Spring Mobile on Red / Black / Blue Wet Pour	Playworld Systems		Satisfactory condition.					
4 x Free Standing Swing Barriers on Grass & Wet Pour	Wicksteed	L	Generally satisfactory but monitor paint condition					
2 x Park Seat on Grass	Macemain	L	Monitor damage/dents repair as required.					
2 x Park Seat on Concrete	Unknown		Satisfactory condition.					
 Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028 www.wicksteed.co.uk		INDICATION OF RISK RATING ASSESSMENT MH/H MEDIUM HIGH & HIGH RISK - See Introductory Notes M MEDIUM RISK - See Introductory Notes VL/L VERY LOW & LOW RISK - See Introductory Notes		INSPECTED BY : C. Newell DATE : 26.1.2016			PARTS SUB TOTAL BALANCE C / FORWARD PARTS TOTAL EXC. CARRIAGE & VAT. LABOUR COST TO FIT PARTS * Based on all works ordered	

Certified Inspection Report For: Llanharry Community Council Groes Sannor, Degar Road Llanharry, Pontyclun, Mid Glamorgan CF72 9JX		Contact: Gill Lewis Tel: 01443 223 007 Mobile: E-mail: llanharrycc@live.co.uk Order No: 322800	Site Address: The Recreation Field (Opp shops) junction of Sycamore Road Ty Isaf, Llanharry CF72 9LJ				SHEET 3 of 3	
DESCRIPTION OF PRODUCTS INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY	PRODUCT CODE	DESCRIPTION OF PARTS REQUIRED	UNIT PRICE	TOTAL
Picnic Table on Tarmac	Unknown		Satisfactory condition.					
2 x Litter Bin on Concrete	Unknown		Satisfactory condition.					
Fence	Unknown		Satisfactory condition.					
2 x Gates	Prosafe	L	Generally satisfactory but recommend the 'second close' is adjusted at both gates to slow the closing rate and reduce potential collision hazards					
Vehicle Access Gate	Unknown		Satisfactory condition (locked at time of inspection)					
Operators Sign	Unknown		Generally satisfactory but the inclusion of emergency service contact number and site address details are recommended (ref: BS EN 1176-7:2008 clause 8.2.4)					
  Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028 www.wicksteed.co.uk		INDICATION OF RISK RATING ASSESSMENT MH/H MEDIUM HIGH & HIGH RISK - See Introductory Notes M MEDIUM RISK - See Introductory Notes VL/L VERY LOW & LOW RISK - See Introductory Notes	INSPECTED BY : C. Newell DATE : 26.1.2016	PARTS SUB TOTAL BALANCE C / FORWARD PARTS TOTAL EXC. CARRIAGE & VAT. LABOUR COST TO FIT PARTS * Based on all works ordered TOTAL COST OF WORKS, EXC VAT	(E&O.E.)	£0.00 £0.00 £0.00 £0.00 £0.00		

